

31 DEC 1952

Received from Chief Ship Surveyor

SHIP'S NAME "ANNA SALEN" REPORT Bmn. No. 520

Outstanding Conditions of Class: Subject to stem, stem and shell plating, etc. being specially examined and dealt with if necessary on vessel's arrival at Le Havre or other European port on arrival from present voyage, also to indented plates A.3 (p.s.f.) K.3 'C' & 'D' strakes in way of Engine Room double bottom tank (s.s.) and 'C' strake in way of No.4 D.B. tank (s.s.) being dealt with by next drydocking.


Endorsement of Class (B) (As before ~~or None~~)

Nature of Present Survey: (Afloat and in dry dock) Docking.
Damage repairs (collision & grounding) and to the stem and stem plating, etc. - part temporary repairs.

Recommendation: SUBMITTED record of docking 10,52 be assigned, subject to indented bottom plating, etc. being dealt with by next drydocking, without other conditions, but with Endorsement (B).

10,52 Bmn. Subject
Without.

ENDORSEMENT OF CLASS (B).
Indents in shell plating (p & s)
Indented sheerstrake plate (s.s.f.).



Temporary repairs in D.B. tank.
Cast steel stem now replaced by mild steel soft nosed stem.

S.S. PART HELD.

003479-003486-0027

The Secretary.