

VRECK

SECTION

No. 1298

4

4th September, 1959.

TERDAM

12, 750, 53, 54, 55, 67, 71, 85, 90,
80 - As recommended.

"DRECHT" 47756 - As recommended.

47764 - As recommended.

783 "HADA" - As recommended, except that the notation SS 1.59 will be assigned when Nos. 8 and 9 main bearings and the independent salt water and fresh water pumps have been examined. In this connection, I have to acknowledge receipt of your letter of the 24th August, the contents of which have been noted.

788 "NARDANA" - As recommended, except that a record of SS 7.59 is also been assigned. I shall be glad if you will issue an amended Interim Certificate to include the additional record of SS 7.59 and fitting reference to part Engine Survey, as the machinery of this ship is being examined on the Continuous Survey basis.

774 "VASUM" - As recommended. In view of the satisfactory nature of the General Examination now carried out at your port, I shall be glad if you will inform the Owners that the Committee have agreed to postponement of the Special Survey until July, 1960.

784 "HYALINA" - As recommended. I shall be glad if you will state the nature of the defects relative to the sea connections.

760 "HULST" - As recommended. I have to advise you that when a subject of class has been dealt with suitable mention should be made in our recommendation to the Committee.

780 "CLYDE" - As recommended. According to the information which is extracted from the First Entry report on this ship there is no auxiliary engine situated starboard aft centre, and I shall therefore be glad if you will indicate the position of the auxiliary engine which is examined at this survey.

7583 - As recommended.



© 2020

Lloyd's Register
Foundation

003479-003486-0184