

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... "ROSA"..... REPORT..... Trd. No. 1387.

Forward and aft. steam generator engines damaged, the forward engine was satisfactorily repaired but replacement parts were not available for the after engine. A portable diesel generator set now fitted temporarily and wired up to shore supply connection,

The Surveyor recommends that the forward generator engine be re-examined, the after generator engine be repaired and the portable diesel generator set removed by 4.58.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED, subject as now recommended.

988. 17.2.58.Lloyd's Register
Foundation

003487-003494-0166

For further particulars see report