

COPY.

LLOYD'S REGISTER OF SHIPPING

Port TRINIDAD, B.W.I.

December 24/57

This is to Certify that I have

surveyed the Machinery of the S.S. ROSA, 3255 gross tons of Port of Spain
on December 18/57 on account of damage to both generator driving engines and
the installation of a portable diesel driven generator,
and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will **Recommend** that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
retained as now Classed without fresh record of survey,

and that her Machinery Classification Record be continued in the Book, subject
to the forward generator engine being re-examined, the after generator engine
being repaired and the portable diesel generator set being removed by 4/58,
(4 months limit)

Parts now examined:

(C.S. Items only)

C. G. Purvis

C.G. Purvis -

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150° F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."