

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

6th March, 1935.

Dear Sirs,

E.

With reference to your report No.13379d on the electrical equipment for the steamer "ROSA", I may say that it is concluded the moving parts of the switches are not alive in the 'off' position, and that no fuses are fitted on the live side of switches, as shown in the approved plan, but I shall be glad if you will kindly confirm this.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
AMSTERDAM.



© 2020

Lloyd's Register
Foundation

003487-003494-0172

COPIES

unpublished to the public

3. C. A. Jones Street, 17

© 2020

Lloyd's Register
Foundation



20

out of the
city of New York

James M. Smith

1875

1875

1875

1875