

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

28th September, 1962.

Dear Sirs,

DEHK/C.  
DET

## CLASSING LETTER

10439 "HENRIK DANICA". As recommended and subject as previously recorded as regards the machinery.

In view of the remarks in your report concerning shell plates B 3 and 4 (portside from forward) which you have recommended to be replaced, it is concluded that these two plates should have been dealt with at this time since they are not included in your recommendation to the Committee, but your confirmation is desired.

It is concluded the screwshaft was in fact magnaflux tested and skimmed<sup>up</sup>, also that the sternbush and oilgland were dealt with as recommended, but please confirm.

Yours faithfully,

pro Clerk to the  
Classification Committee

The Surveyors,  
LE HAVRE.



© 2020

Lloyd's Register  
Foundation

003487-003494-0231