

The class is subject to the main engine LP cylinder foundation
(starboard side) being specially examined by 12.57.

9 JAN 58 **4E**

Inspected by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME..... PRECILA REPORT Smk No. 794


E.S. due 4.57 duty held 7.57 not advanced.

SRL The above item dealt with and the Surveyor recommends
a further examination by November 1958 (12 months
limit).

IT IS SUBMITTED this vessel is eligible to
remain as classed subject as now recommended.

JW

1.1.58.



© 2020

Lloyd's Register
Foundation

003495-003502-0186