

alterations in the existing records should be underlined.

Port, No. 8301 Port Lon

100 AL

8.52 - Lon.

Received from Chief Ship Surveyor 17 FEB 1954

E "LARCHOL" REPORT Cff. No. 58636

Conditions of Class: Subject to permanent repairs to indented shell plating, etc. in way of Pump Room forward bulkhead (s.s.) on ship's arrival at a Bristol Channel port from present voyage.

t of Class (B) (As before on ~~None~~)

Present Survey: (Afloat and in dry dock)

Docking.

Damage repairs (contact) to the indented shell plating (s.s.) as above.

tion:

SUBMITTED record of docking 1,54 be assigned, without special condition, but with Endorsement (B).

1,54 Bry. Without.

ENDORSEMENT OF CLASS (B).

Indents in sheerstrake (p & s).



© 2020 12-2-54

Lloyd's Register Foundation

003503-003512-0047

efficient ?

Treenails

Breasthooks & Stenson

Anchors, No.

Cables (State i

length