

11 3 MAR 1959

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... STELLA DORADO..... REPORT Hull No. 64756

MBS due 4.59, now held.

The Surveyor reports some repairs effected to the back end plate of the main boiler on account of grooving in the radius of the flange; the end plate cropped and satisfactorily part renewed.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of MBS 2.59.



2020
Lloyd's Register
Foundation

10.3.59

003513-003524-0055

Parts now examined: