

16 JAN 1963

CABLE OUT

546

V
OSEAGRAM L F R
COMMITTEE LDN
OSEAGRAM L F R

24305 COMMITTEE LDN

MARINE HONGKONG=

LEEFOON REURCAB 15TH IN VIEW EXTENT DAMAGE PREVIOUSLY REPORTED
AND LIKELY REPAIRS SHIP SHOULD BE OPENED UP EXAMINED AND TESTED
AS FOR COMPLETE SPECIAL SURVEY ALTHOUGH RECOMMENDATIONS MAY BE
LIMITED TO THOSE REPAIRS CONSIDERED ESSENTIAL FOR 12 MONTHS
THUS CONSTITUTING MODIFIED SPECIAL SURVEY STOP GENERAL EXAMINATION
MACHINERY REQUIRED AND ATTENTION TO PREVIOUS RECOMMENDATIONS
REGARDING STARBOARD BOILER FURNACES ALSO BOILER SURVEY SHOULD
BE COMPLETED WRITING = COMMITTEE +

CT 15TH 12 +

24305 COMMITTEE LDN

OSEAGRAM L F R
SENT 4.30

PLEASE READ IN PENULTIMATE LINE BOILER FURNACES

OK PSE??



© 2020

Lloyd's Register
Foundation

003513-003524-0251

SS notation with note for 12 months 15/1/63

16/1/63

blissing



© 2020

Lloyd's Register
Foundation

COBA