

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

9th November, 1962

C  
EJB/RW

Dear Sirs,

Steamer "LEEFOON"

Your Report No. 17301 has received the consideration of the Committee today.

In view of the fact that the damages as now found by you are such as to adversely affect both the seaworthiness and the strength of the ship, and that you recommend further examination and repairs as considered necessary before the ship leaves your Port, the Committee feel that the position should be reflected in the Register Book, and they have therefore given instructions for the notation "Repairs required - class suspended 11.62" to be recorded in the Register Book.

I shall be glad if you will inform the Owners accordingly.

Yours faithfully,

Deputy Clerk to the  
Classification Committee

The Surveyors,  
HONG KONG



© 2020

Lloyd's Register  
Foundation

003513-003524-0254