

COPY

# LLOYD'S REGISTER OF SHIPPING



Rpt.No.D.8102

Port of Piraeus,

29th July, 1959.

This is to Certify that

E.F.Reid

the undersigned Surveyor to this Society did at the request of J.A.Saunders, Esq., Lloyd's Agent, Piraeus, and with the consent of the Owners' Representative attend on board the

S.S."LEONIDAS"

4573 tons gross of Andros

whilst lying at Piraeus on the 23rd & 24th July, 1959 on account of Fire damage stated sustained on the 23rd July, 1959 at Piraeus (cause unknown).

It was stated that the vessel was tied up at No.11 dock Piraeus whilst carrying out Boiler repairs before proceeding to sea, and watchman being kept on board during the night. At 06.00 hours of the 23rd July, 1959 the watchman noticed smoke issuing from the poop door and opened same to investigate but could not see anything due to the smoke and called for assistance and was answered by the tug "KENTAVROS" who come alongside and extinguished the fire by 07.00 hours (cause unknown).

For further particulars see watchman's statement.

Upon examination by the undersigned the following damage was noted and repairs recommended without prejudice to the terms and conditions of insurance.

FOUND:

The fire was contained in the poop which was used for a store. The aft part was divided by a wooden bulkhead, and contained bonded stores sealed by the Greek Custom Authorities.

FOUND:

Wooden bulkhead burned and charred. To renew.  
Several wood shelves charred and burned. To renew.

RECOMMENDED:

To renew.  
To renew.

Cont/...

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



S.S. "LEONIDAS"

FOUND:

Deck head covered in soot  
and badly damaged with water.

RECOMMENDED:

Poop space to clean and repaint.

The following list of items was submitted by the Owners  
Representative as having been within the space and damaged.

Paints:- White enamel Gal.180  
Green Gloss Paint Gal.80  
Red lead Gal. 100  
Assorted paints Gal. 20  
Linseed Oil 9 tins and 1 barrel Gal. 86  
Varnish Copal Gal.14  
Fish Oil 2 barrels Gal. 90

Ropes:- Manila 3" 8 coils, 720 fms.  
Heaving lines 2 coils, 180 fms.  
Log Line 1 coil, 120 fms.  
~~Wire rope 3" x 10 coils, 360 fms.~~  
~~Wire rope 1" x 10 coils, 120 fms.~~  
~~2 x fire extinguishing uniforms~~

2 fire extinguishing uniforms complete with helmets and  
accessories.

6 tarpaulins new 22' x 32' each.  
2 pots aluminium paint Gals.4.  
Cotton waste lbs. 450.  
Tar impregnated caulking hemp. lbs.240.  
Turpentine 6 flasks Gal. 60.  
4 doz. paint brushes 4" flat.  
20 pieces oval brushes 3"  
8 pieces oval brushes 2".  
2 doz. cement brushes.  
Various brooms about 25 pieces.  
White lead powder 4 barrels.  
2 new spare lifeboat covers.  
6 new spare ventilators covers.  
2 rolls 80 yards white canvas.  
8 pieces roller brushes.  
6 lengths canvas hoses 2 1/2".

The Owners stated that only cleaning and painting of the poop  
space would be carried out and this was done at an estimated  
cost of Drs. 5.000 with three days to complete.

No items were replaced at Piraeus before the vessel's  
departure.


The above recommendations were made with a view to placing  
the vessel in the same good and efficient condition as before  
the alleged casualty occurred.

In the opinion of the undersigned the above damage is reasonably  
consistent with the alleged cause.

Survey Fee £ 10. 0. 0  
Stamps 2. 9

£ 10. 2. 9 at Drs. 84,76 per £ = Drs.859,30

*E. J. Reed*  
Surveyor to Lloyd's Register.



Lloyd's Register  
Foundation

0282 2 1/2