

16th August, 1960.

TRADE

523, 25, 39, 41, 63 - As recommended.

MC 8559 - As recommended.

8531 - As recommended. I acknowledge receipt of your letter of the 19th July the contents of which have been noted.

533 "SUEZ" - As recommended, except that the set in No.4 plate in st and 2nd strakes below sheer with structure in way (port side forward) should be specially examined and dealt with as necessary by the Special Survey.



© 2020

Lloyd's Register
Foundation

003525-003532-0097