

111 AUG 1960

SHIP'S NAME "SUEZ" REPORT PIR No. 8533

standing Conditions of Class: SUBJECT to shell plating No.3 & 4  
in 1st below sheer (s.s.f) and shell plates Nos.4 & 5  
(s.s.a) being specially examined and dealt with as  
necessary by the next drydocking.

L. Appendix. (~~As before~~ or None)

Condition of Present Survey: (~~Afloat and in dry dock~~)

Docking: Permanent / deferred wear and tear repairs.

Recommendation:

SUBMITTED record of DS 6,60 be assigned, subject  
as above and to set in No.4 plate in 1st and 2nd strakes  
below sheer with structure in way (p.s.f) being  
specially examined and dealt with as necessary by the  
Special Survey.

As Now SUBJECT.



Att  
21/7/60 2020

Lloyd's Register  
Foundation