

3m.7.28.

1

* Lacklan *

Sent to Chief Surveyors


Received from Chief Surveyors

VESSEL'S NAME *Stl & VACUOLINE*Report *LK*No. *18996***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Clasing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey *1st Entry*When due *Revised Rules*

✠ 100A.1. (Steel). carrying Petroleum in bulk.
 2 D⁴ (Stl) web frames, longitudinal framing. Bracketless Systems
 Cell D.B. & E.B. 65' + 27' 280t, F.P.T. 190t, A.P.T. 130t.
 F.K., 18 B.H., pt cem pt asp, Lloyd's A.C.P.
 P 118', B 42', F 41', machy app.



© 2021
 Lloyd's Register
 Foundation

003534-003840-0132

Floors, Depth and thickness at mid-line in

Holds

in way of Bridge, Angle