

003534-003540-0167

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME LACKLAN

REPORT Bremen

No. 1021.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

# COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey, due 5.54 ~~now~~ partly held 7.53, now completely held  
~~completed~~, and the following repairs carried out (due to WAT) :-  
 Some main bearings re-metalled. Propeller renewed.  
 A number of main condenser tubes renewed

© 2021

It is submitted the vessel is eligible to remain as classed, with  
 station of + LMC 9.54 and SPS 5.50. as recommended.  
 It is concluded the Centre boiler was examined  
 but, this should be confirmed ~~yes~~

Lloyd's Register  
 Foundation  
 25/10/54  
 72/110