

003534-003540-0260
Received from Chief Ship Surveyor

25 JAN 1955

JD. SHIP'S NAME "RONA" REPORT Syd. No. 27788

Outstanding Conditions of Class:ACTION is DEFERRED for examination
in drydock after grounding.Endorsement of Class (B) (As before ~~XXXXXX~~)Nature of Present Survey: (Afloat and in dry dock)Docking and repairs.
Alterations in accordance with approved plan attached.Recommendation: SUBMITTED record of docking 11,54 be assigned,
subject to fractured hawsepipe (s.s.) being renewed
and permanent repairs being effected to casing top
by next Special Survey, also to wing tanks in No.2 hold
not being used for liquid cargoes until satisfactorily
tested.

11,54 Syd. Subject.

~~ENDORSEMENT OF CLASS (B).
Indents in shellplates (p & s).~~~~DELETE FROM S.R.L.
Drydocking (grounding).~~

✓ AMEND R.B.

From: Carrying molasses in top side tanks.
To: Carrying molasses in top side tanks and in ^{side} wing tanks in
Nos.2 & 3 holds.

Decks Good Bulkheads See Rpt. Good Engine Room Skylights Good



© 2021

Lloyd's Register
Foundation*[Handwritten signature]*
19/1/55