

to Chief Surveyors.....

Received from Chief Surveyors.....

NAME "TANLAN" REPORT Liv. No. 146265.

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

of Survey Docking. Deferred When due
damage repairs.

NOTED

SUBJECT to indented shell plate No.5 etc.
in main sheer (p.s.a.) also to set up shell plates
B.2 & C.5 and adjacent 'B' strake plate (s.s.a.) being
examined and dealt with as necessary at the Special
Survey also to 15 fathoms of chain cable being supplied
at the earliest opportunity.

ENDORSEMENT OF CLASS(B).

Indented shell plating (p & s).

AM-9
3.57



© 2020

Lloyd's Register
Foundation

003541-003548-0268