

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

14th September, 1962

R.  
SEI/BJs

Dear Sirs,

s.s. "FUKUYO MARU"

As a result of the survey held at Sydney in July the hull class has been continued subject, inter alia, to leaky bottom shell plating in way of cofferdam between frames 67/68 (p and s from aft) being specially examined and dealt with as necessary by the end of September, 1962.

I shall be glad to learn as soon as possible what definite arrangements can be made by the Owners for this matter to receive attention.

It will also be appreciated if you will advise the Owners that the Main Boiler Survey will become due at the end of December next.

Yours faithfully,

Clerk to the  
Classification Committee

The Surveyors,  
KOBE



© 2020

Lloyd's Register  
Foundation

003549-003555-0209