



Lloyd's Register of Shipping,

342, Argyle Street, Glasgow, C.2.

30th May, 1929.

Dear Sir,

In reply to the London letter of the 28th instant having reference to the Glasgow Report No. 49218 on the Exhaust Turbine Installation No. 8, I beg to state that I have to-day made enquiries and find that the correct diameter of the intermediate shafting is $12\frac{1}{4}$ " not 12" as given.

I regret the error and shall be glad if the correction can be made in the above report.

I am, Dear Sir,

Yours faithfully,

A. Campbell

The Secretary,

GLASGOW.

782



© 2020

Lloyd's Register
Foundation

003549-003555-0228

20

Noted
JRW
31.5.29

soft wax, 1353.



© 2020
Lloyd's Register
Foundation

In reply to the Town letter of the
28th instant relating to the
1st class engine installation no. 8, I beg to advise you
of the following statement made
to the engineer of the
Tyneside and Tees
Co-operative Society
on the 2nd instant.

I understand the letter was sent to you.

Yours faithfully,

A. H. STANNETT,

The Secretary,
DRAWN.