

COPY.

Lloyd's Register of Shipping.



Port

PORT SAID

8th February 1949

This is to Certify that I have

Surveyed the Steel Sc. M.V. "ATLANTIC QUEEN" 15300 tons gross

register of Kungsbacka whilst lying afloat at Port Said for damage to shell plating, guard rails, poop deck plating and starboard gangway stated to have been sustained on the 8th February 1948 during squally weather in Port Said Harbour when the s.s "Singkep" is alleged to have contacted vessel,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as at present

classed in the Register Book, without fresh record of survey.

being fit to carry Petroleum in bulk.

(See other side.)

J. de Wae
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

COPY.

Lloyd's Register of Shipping

Repair starboard gangway, buckled gangway davit, set in upper edge of shell plating (1st strake above sheer) on starboard side in way of poop and set down deck plating in way at Owners convenience.

Port

J. de Kuy

PORT SAID

8th February 1949



This is to Certify

that I have

Surveyed the vessel "ATLANTIC QUEEN" 12300 tons gross register of Kungsbacka whilst lying at Port Said for damage to shell plating, guard rails, poop deck plating and starboard gangway stated to have been sustained on the 8th February 1948 during equally weather in Port Said Harbour when the s.s. "Sinking" is alleged to have contacted vessel.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have recommended that she be continued as at present classed in the Register Book, without fresh record of survey.

being fit to carry Petroleum in bulk.

(See other side.)

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."