

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw Trawler "LOCH MONTEITH" Rpt. Mdb. No. 15737

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2700

Depth "d" --

2nd Long. No. 7425

Proportions = $\frac{L}{D}$ --

Framing Angle frames as approved
Reverse frames fitted
every fourth frame

Sheerstrake As approved (+.08)

Additional stiffening has been fitted to the shell and
deck in excess of the scantlings indicated on the approved plans.

This vessel appears to have been built in accordance with the
Rules and the approved plans, and it is submitted she is eligible to
be classed

100A1 Steam Trawler

1 Dk.

Side Tanks in E.R. 10t, DTf 7' 25t, APT 9t.

BK 7 $\frac{1}{2}$ ", 4 BH, Cem. Lloyd's A& CP.

Q 36', F 32'.



9.7.36.



© 2020

Lloyd's Register
Foundation

003581-003590-0036

2.P.