

LLOYD'S REGISTER
RECEIVED
4 - FEB 1936
Ansd. *14*
LONDON

4 FEB 1936

(Received at London Office)

REQUEST FOR INSPECTION SERVICES.

DATE 3rd February, 1936.

We confirm our request to the Committee of Lloyd's Register, that they will instruct the Society's Surveyors to inspect Superheater Apparatus for Messrs. *Yard No. 1002-3-4-5* Smith's Dock Co. Ltd., Engines Nos. 461, 462 463 and 464.

at AS BELOW.

and we agree to pay the ~~fee and expenses~~ inclusive charge of £3.3s.0d. incurred for these services.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Hall

NAME OF FIRM THE SUPERHEATER COMPANY LIMITED,

ADDRESS MOSLEY ROAD, TRAFFORD PARK,

MANCHESTER. 17.

After signature, please return this form to:—

THE SECRETARY,
LLOYD'S REGISTER OF SHIPPING,
71, FENCHURCH STREET,
LONDON, E.C.3.

(Req. 8a). 1500, 1935.



© 2020

Lloyd's Register
Foundation

003581-003590-0041

If not, state whether, and when, one will be sent

In a Report also sent on the Hull of the Ship

could be deleted

ST 11

spe

