

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic (Inland: Committee, London, Telex
Address (Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

23rd January, 1962.

C
AH/HW

Dear Sirs,

Steamer "LOCH MONTEITH"

The Society's Surveyors at Bergen have reported that this ship was under survey last month when temporary repairs were carried out to indented and fractured shell plating.

It was recommended that indented and fractured shell plating port and starboard aft and set over stem and stem plating etc. should be specially examined and dealt with as necessary at the next drydocking by September, 1962. The Committee have continued the class subject to this matter receiving attention by that time..

In the meantime a fresh record of drydocking 12.61 has been assigned.

Yours faithfully,

Deputy Clerk to the
Classification Committee.
The Loch Fishing Co. of Hull, Ltd.,
St. Andrew's Dock,
HULL.

Dictation Time 9.40 - 9.46



© 2020

Lloyd's Register
Foundation

003581-003590-0064