

Received from Chief Ship Surveyor.....

TR JAN 1962

SHIP NAME "LOCH MONTEITH" REPORT Bgn. No. 4896
GB.

Standing Conditions of Class: NONE.

U.L. Appendix. (~~As before~~ or None)

Duration of Present Survey: (Afloat and in dry dock)

Docking: Temporary repairs on account of leakage.

Recommendation:

SUBMITTED record of 'DS 12,61' be assigned as recommended, subject to indented and fractured shell plating (p.& s.a) and to set over stem and stem plating etc. being examined and dealt with as necessary at the next drydocking by 9,62.

DS 12,61 Subject



©

W.O.I. ✓
2020
9.7.62.

Lloyd's Register
Foundation