

F.E.

Ship Surveyor _____

Received from Chief Ship Surveyor _____

E Stl & "LADY OLGA" Rpt. Sld No. 29528

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points set out in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

erse No. 3885 Depth "d" _____

g: Table No. ✓ Description Bull angle frame as approved

udinal No. 11918 _____

Proportions Length 12.99 to M.D.
Depth = _____

Deck Sheerstrake as approved

Revised Rub

This vessel appears to have been built in accordance with the _____ and the approved plans, and it is submitted she is eligible to _____
assed

✠ 100 A. I. (Steel)

1 D* (Ste) Well D*

Cell D.B. & E 20' + 139' 328t, D.T. + 7' 115t, F.P.T. 169t, A.P.T. 235

F.K, 5 B.H, Cem, Lloyds A.C.P.

Q 127' B 16', F 24' machy aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

[Signature]

11.10.27.



© 2020
NOTED TRO
Lloyd's Register Foundation

003581-003590-0255