

COPY.

## LLOYD'S REGISTER OF SHIPPING



RPT. No. 31378.

Port BUENOS AIRES

11th March, 1960.

LOADING CERTIFICATE FOR CLASSED REFRIGERATED  
CARGO INSTALLATION

The temperatures in the chambers were noted to be as follows:-  
 NAME OF SHIP T.S.M.V. "LEME", 8039 tons gross of Genoa.

This is to Certify that I have examined the Refrigerated Cargo Installation of the above named ship as stated below for a Loading Port Survey as required by the Society's Rules.

The installation is classed with the Society and has the survey record of LLOYD'S RMGS 9.59 in the latest Supplement to the Register Book available at this Port. A certificate on board dated \_\_\_\_\_ issued at the Port of \_\_\_\_\_ states that a later record of LLOYD'S RMC \_\_\_\_\_ has been recommended.  
 "to maintain temp. 15°F with sea temp. 86°F, maximum"

The chambers specified overleaf and their equipment, together with the refrigerating plant under working conditions, have been examined by me in accordance with the requirements of the above-mentioned Rules, and in my opinion, are in a fit and efficient condition.

I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me haven been completed to my satisfaction.

Before loading was commenced, the temperature of the cargo chambers was reduced as shown overleaf.

*W.P. Rogerson*  
 Surveyor to Lloyd's Register of Shipping.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, of the Surveyors, or other Officers or Agents of the Society."

COPY

The following chambers have been examined: FLOYD'S

AS BELOW



LOADING CERTIFICATE FOR CLASSED REFRIGERATED CARGO INSTALLATION

The temperatures in the chambers were noted to be as follows:—

No. 5 Chamber.....to -12°C.

The installation is classed as a chamber and the temperature in the chamber was noted to be as follows:—

I have submitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me have been complied to my satisfaction.

While the certificate of the Society is issued, the Committee of Lloyd's Register of Shipping, London, is not responsible for any loss or damage to the cargo.



© 2020 Lloyd's Register Foundation