

by Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME

"LEME"

Rpt.

Gen. No. 15109

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to 15 fathoms of chain cable being repaired and replaced.

The Genoa Surveyors report the vessel placed in dry dock, the bottom cleaned and coated and minor repairs effected.

A repaired length of chain cable now on board as above, examined and found satisfactory.

It is stated the 1st S.S.No.3, due 10,37, will be held on the vessel's return to Trieste for re-engining, in a few months, and in the Surveyors' opinion this merits favourable consideration.

It is submitted action be deferred.

Delete from S.R.L:- Chain cable.

20.12.37



© 2020

Lloyd's Register  
Foundation

003599-003604-0013