

the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and

687 130/140
Man Engine No. _____ Made by man.

Jeuthe West No 181

Bruce Report No. 1886

It is submitted that a copy of this Report be forwarded to the _____ Surveyors for their guidance and for completion.

copy Report
Ham 25/3/37
181 per R.F. Transcript

Mun
Date 17.3.37

~~It is concluded these engines are for Jeuthe West No 181 but this should be confirmed~~

all Sea Connections fitted direct on the stern of the ship
they fixed sufficiently high on the ship's side to be seen without lifting the platform plates Are the Overboard Discharges above or below the

003599-003604-0306

