

Received from Chief Ship Surveyor

14 JUN 1961

SHIP'S NAME "PARNASSOS"

REPORT ROT

No. 51530

EA

SUBJECT to bottom plating forward and shell outstanding Conditions of Class: plates Nos.10 & 11 (p.s) with internals in way, also to indented shell plates Nos.3,4 & 5 in 1st below sheer (p.s.f) also No.5 in 1st below (p.s.a) being specially examined and dealt with as necessary next drydocking, and to set in 'K' strake plating etc.in way of steering gear compartment and adjacent tank (s.s.a) and to buckled stem plating etc., also indented shell plating (s.s.f) being specially examined and dealt with as necessary by 4,61.

S.R.L. Appendix. (As before ~~or None~~)

ature of Present Survey: (Afloat and in dry dock)

Docking:- Permanent repairs to damage on account of grounding etc. including S.R.L. and S.R.L.Appendix items.

ecommendation:

SUBMITTED record of DS 4,61 be assigned, without special conditions.

DS 4,61 Without.

DELETE S.R.L.APPENDIX.



© 2020

Lloyd's Register
Foundation

003599-003604-0328