

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address: Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

8th February, 1963.

Dear Sirs,

CLASSING LETTER

"JAG MATA". Reverting to my letter of the 25th January, the report of a survey held at Madras has now received the consideration of the Committee, but the Main Boiler Survey was not completed as agreed.

To complete the survey for a notation of MBS 6.62 all centre boiler mountings and safety valves require to be examined and safety valves to be adjusted under steam. You should inform the Owners accordingly and let me know as soon as possible what definite arrangements they now propose to make for completion of this overdue survey.

As a result of the survey held at Madras class has been continued subject, inter alia, to the centre boiler combustion chamber wrapper plates, being specially examined after descaling by the end of March 1963.


I think it well to add that if the centre boiler is re-examined when the condition of class is dealt with a later notation could be assigned if the other two boilers are also examined at the same time.

Yours faithfully,

The Surveyors,
CALCUTTA

pro Clerk to the
Classification Committee

The Surveyors,
CALCUTTA.



© 2020

Lloyd's Register
Foundation

003605-003610-0082

003605-003610-0081