

Ship's name

JAG MATA

Port

MDR.

No. 1765

6-FEB 1963

Last survey date 29/1/63

Ship is subject to :-

Endless port gyrry shaft main bearing pedestal and clutch support being repaired at the next dry docking

MBS due 5/62, commenced 6/62 and subsequently

Now advanced

The Surveyor reports the boiler not cleaned sufficiently on water side in way of combustion chamber wrapper plates which were noted somewhat wasted around C.C. stays. and he recommends the Centre boiler combustion chamber wrapper plates being specially examined after de sealing by end 3/63.

It is submitted that the

MBS 6/62

in the survey has been completed.

Subject as above and as now recommended

To complete MBS :- all centre boiler mountings and safety valves to examine and S.D. adjust under steam.

Let the centre boiler is re-examined when subject item being all with then a later record could be assigned if the other boilers are also examined at the same time

003605-003610-0083

noted
P. R.

003605-003610-0007

6/2/63