



NYON w/s ~~716~~

M/M. 3609

*Any openings not shown on this approved plan which may be cut in bulk deck or shell plating are to be properly framed and adequate compensation provided to the surveyors' satisfaction. The loss of sectional area of longitudinal material is to be restored by doublings or increased thickness of plating in way of, and around, such openings.

Adequate compensation is also to be fitted for the cutting of other strength members in the structure as may be necessary.

Adequate compensation is also to be fitted for the cutting of other strength members in the structure as may be necessary.

85/3/19
BELONGS TO
ROTTERDAM REPORT No. 47734

LONDON COPY

SHELLPLATING AND DOUBLE BOTTOM.

N.V. BOOLE'S SCHEEPSWERVEN EN MACHINEFABRIEK
BOLNES (HOLLAND)

SCHAAL 1:100.	DATUM	AFDELING: SCHEEPSBOUW.	TEKENING No.
---------------	-------	------------------------	--------------

GET. : A.H.B.	29-1-'59	BESTEMMING:
---------------	----------	-------------

M.S. "NUON." R.770-5

003605-003610-0183