

13 JUL 1962

Received from Chief Ship Surveyor.....

NAME "NYON" REPORT Ant. No. 37827

inding Conditions of Class: SUBJECT to indented shell plates
Nos. 4 & 5 in 4th strake below sheer (s.s. from fwd) and to
sternframe (E.W.9,61) being specially examined and dealt with
as necessary next drydocking.

Appendix. (~~As before~~ or None)

of Present Survey: (~~At float~~ and in dry dock)

Docking: Damage repairs (various causes) and to the deferred items
as above.

Damage involving stem and stem plating and 'F' & 'G' strake
plating (p.s.) in way of No.4 hold.

endation:

SUBMITTED record of 'DS 6,62' be assigned,
subject to stem and stem plating and 'F' & 'G' strake
plating (p.s.) in way of No.4 hold being examined
and dealt with as necessary at the next
drydocking, but without other condition.

DS 6,62 Subject
Without.

INSERT IN S.R.L. APPENDIX.
Sternframe E.W. 9,61.



© 2020

Lloyd's Register
Foundation

S.P.K.
6/7/62

005605-003610-0210

3
iter

; Co

wca

awa

h.

UAT