

as: Nymdible, New York

Telephone: WHitehall 4-0220
4-0221
4-0222
4-0223

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

17 Battery Place,

New York 4, N. Y.

AIR MAIL

RECEIVED

28 JUN 1962

June 26, 1962

The Secretary

LONDON

M. S. "NYON"

Dear Sir:

I have your letter of the 12th instant re-
garding Tampico Report No. 8, and have to say that
the surveyor has stated that the main engine No. 2
top end bearings were found with the Babbitt wasted
and broken, and for this reason he recommended their
renewal at the next port.

Yours faithfully,

L. J. Lister
Secretary to the
American Committee

WGS:JHG



© 2020

Lloyd's Register
Foundation

003605-003610-0211

4/13

AMERICAN COMMUNITARIANISM

SECRET

DEWIL 212:

the secret of

Soer Mul 85

NEW YORK F. N. Y.

PLA JIA

202

Lloyd's Register
Foundation

Yoto

Examination and simplified if necessary could be summarized on account of repairs done. Repairs done would be summarized in a table relating to drill holes. Variables are reproducible which is to be a