

motor
p.m., G
a St.
nots.
tank st
p.m., G
Abb's
motor
M.T.:
on, proo
om Ny
nd, no
salvage
n Ston
T.: Fol
Head lif
nd pro
m Bro
listant.
om Ny
ion two
lead, re
No. 2.
m Ston
received
ifeboat
e are st
of a r
y closer
om N
nd now
d.
tio, No
Swiss
p.m.,
master
ast 200
ples. V
'mids
I and
er high
r. 16.—
receiv
el Ny
gently
and 1
salvage
gs from
16.—T
y Swis
agroun
oastgu
holed.
refloat
cemen
d.
v. 16.
Simson
u Wij
v. 16
t on t
coast
dense
in bo
The
te dan
air th
ving v
ing a
on a cl
lay. T
Watso
l, abou
el lies
pea
ne sho
ce 150
to sa
the l
off the
Tyne
b, wi
Nearly
by bag
nes b
at alo
ssel E
st an
ding.
yon s
i worl
ows
the w
side
have
an ex
holds,
LLOYD'S

STED 1/p.

LLOYD'S REGISTER OF SHIPPING

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telephone: ROYAL 9165

Telegrams: Committee, Fen, London

20th January, 1959.

Motorship "NYON"

Classn(S)
RNC

Dear Sirs,

Motorship "NYON"

With reference to the unfortunate casualty sustained by this vessel last November, the Committee have now had before them the question of the notation to be recorded in the Register Book.

The They have been informed that the after part was towed to Newcastle after being cut away from the forward section, and they have given instructions for the class in the Register Book to be deleted by the assignment of a notation "Broken in two 11,58."

Yours faithfully,

Clerk to the
Classification Committee

Messrs. Suisse Outremer S.A. de
Gerance et d'Affretement
Maritimes,
13, Quai de l'Ile,
Geneva,
Switzerland.



© 2020

Lloyd's Register
Foundation

both taking water.—LLOYD'S
respondent.