

4E

23 JUL 1957

YOer Surveyor

Received from Chief Engineer Surveyor

ANNIE JOHNSON

REPORT GOTH.

No. 23391

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the

"- Extract from Sub-Committee's Report, 24/5/92)

PAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

has notation "Laid up - Surveys overdue"

, DBS + Docking now held.

engines renewed (2)

shafts renewed (2)

aux. engine replaced by reconditioned (LR) engine.

It is submitted that
this vessel is eligible for
THE RECORD.

ES 6.57

TS 04 (p+s) 6.57 (Both N)

DBS 6.57

notations in RB as follows:



6.57 "

Engines 4SA each 6 Cyl. 400x460 mm.

hydraulic coupling & S.R. gearing to 2 screwshafts.

el Maschinenbau G.m.b.H., Hamburg "

ic) "

2020
23 JUL 1957Lloyd's Register
Foundation

003605-003610-0275