

Rpt. 19

Date of writing Report 6th. June, 1962 Received London Port BUENOS AIRES No. 33965

Survey held at BUENOS AIRES No. of Visits one First Date and Last Date 6-6-62

REPORT OF SURVEY ON REFRIGERATED CARGO INSTALLATION BEFORE LOADING

No. in Register Book 01793 Name of Ship T.S.M.V. "ANNIE JOHNSON" Condition as shown in Register Book or as amended in Supplement +LLOYD'S RMC (RS)2,61 (A Certificate on board dated 12-4-62 issued at the Port of Stockholm states that a later record of +LLOYD'S RMC (RS)4,62 has been maintained temp. 10°F. with sea temp. 86°F. max. + " /recommended) Capacity of refrigerated cargo space 47300 cu.ft. Total No. of independently refrigerated chambers 2 No. 13564 Port Lsm filled in at Head Office)

CONDITIONS FOR LOADING PORT SURVEY

Chambers specified below, with their air cooler spaces and air ducts (where fitted), been examined in an empty state and found clean and free from which would adversely affect the cargo; the air cooler fans and motors (where fitted) been examined under working conditions and found or placed in good order; the brine or other refrigerant pipe grids, valves and connections been examined and found free from leakage; the thermometers with their connections and fastenings, the fixed cargo battens on the vertical surfaces, the lashing and dunnage battens provided for the floors or decks as required to suit the class of cargo been examined and found or placed in good order; the insulation linings and coverings been examined and found free from damage; the scuppers and bilge suction drains draining insulated spaces been examined and found or placed in good working order, the liquid level, and the refrigerating plant been examined under working conditions? Yes

Table with 6 columns: Chambers examined, Temperature when noted, Chambers examined, Temperature when noted, Chambers examined, Temperature when noted. Rows include Lower Twn. Dk. (0°C) and Hold (-16°C).

All except minor repairs, or the whole or part of other Surveys which may have been carried out, or any action taken to impose, amend or delete special conditions of class, are to be reported on Rpt. 18.

If survey is not complete state what arrangements have been made for its completion and what remains to be done Complete

Has a certificate been issued and a copy attached to this report? Yes

RECOMMENDATION AS TO CLASS (special conditions of class to be stated.)

RECOMMEND THIS INSTALLATION REMAIN AS CLASSED Without fresh record of survey

Insurance Fee \$ 3,610.00 Expenses (if chargeable) \$ 850.00 \$ 100.00

Date Account rendered 6th. June, 1962

Date of Committee THURSDAY 28 JUN 1962

Minute as now subject.

It is submitted that the
vessel's REFRIGERATING IN-
STALLATION is eligible to
remain as classed.

Subject as before,

End
25/12/62



© 2020

Lloyd's Register
Foundation