

4E

is subject to

Scum valve chest of No. 7 Centre After Main Boiler being specially examined at the next MBS (welding repairs).

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

13 FEB 1962

P'S NAME..... "ORONTES"..... REPORT..... SYD..... No. 34597.

MBS due 10.61. Partly held 12.61. Not advanced.

The Surveyor reports back end plate of No. 4 Main Boiler found fractured at bottom radius below centre combustion chamber and the fracture cut out and built up by electric welding and upon completion of repairs the Boiler examined under steam and found good but the Surveyor recommends that the class be made subject to No. 4 Main Boiler back end plate being specially examined at the next Main Boiler Survey.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as recommended and as above.



© 2021

13.2.62.

Lloyd's Register
Foundation

003620-003624-0075

