

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

30 JUL 1957^{4E}

NAME PARKWOOD

REPORT

Hpl.

No. 19813

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24(5/52.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH


ES due 6.57, now held.
MBS due 3.57, now held
DBS due 3.57, now held.

Docking. Screwshaft seen. Steampipes seen.

Repairs.

IT IS SUBMITTED this vessel is eligible
for the records:

ES 6.57
MBS 6.57
DBS 6.57
SPS 6.57
TS(CL) 6.57

 16.7.57.



© 2021

Lloyd's Register
Foundation

003620-003624-0191