

94  
10644

Depth, at middle of length from top of keel to top  
of beam at side of uppermost continuous  
deck. See Sec. 3 (1c)

D 39.25'

34204

WIRE.

SUBMITTED the New York Office be informed  
that there is no record in this Office of the  
to which they refer regarding the thickness  
of tubes in T2 Tankers.  
Owners should be requested to state  
the thickness of tubes and ~~proposed~~ working  
when the matter would receive consideration,  
and confidently stated that the classification  
of vessel would not be withheld because  
of boiler tubes which had proved  
in service.

W. J. F.

6.3.47.

Discussed verbally with Mr. Lamb,  
Chief Engineer, who is quite clear  
on the position.

WJF

7/3/47



© 2020

Lloyd's Register  
Foundation

003631-003639-0020

Flat Plate Keel Angles

Fourth Deck, amidships, A