

68.2

39.2

Draught Moulded

Do.

Long Bridge to
top of keel }

20'-1 1/4"

surveyed while
adfloat

COPY

AMS.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

NLT

NYMDIBLE NEW YORK

(7. 3. 47.)

WORTH REGARDING T2 TANKERS NO RECORD HERE OF ANY DISCUSSION
THICKNESS BOILER TUBES STOP SOME TANKERS OF THIS TYPE
TRANSFERRED LLOYDS REGISTER CLASS FOR ANGLO AMERICAN NAMELY
AND WAUHATCHIE STOP GIVE DIAMETER THICKNESS TUBES AND
PRESSURE FOR CONSIDERATION BUT CONFIDENTLY STATE
SITUATION EXISTING SHIP WOULD NOT BE WITHHELD ACCOUNT THICKNESS
TUBES WHICH HAD PROVED SATISFACTORY IN SERVICE STOP ANGLO
DO CLEAR ON THIS POINT AND CHIEF SUPERINTENDENT HAS ADVISED
TO TRANSFER CLASS LR ON COMPLETION PURCHASE

COMMITTEE



© 2020

Lloyd's Register
Foundation

003631-003639-0023

COM.

th and thickness at mid-line in

Wells, Angle, [or]

in way of Bridge, Angle,

[or]