

Copy for.....Department

Original letter with: "STANVAC MELBOURNE"

~~Copy of~~ Extract from letter received from

NAME Surveyors,

ADDRESS Kobe.

Reference, if any:.....

Dated 18.12.52 Received 29.12.52 Answered.....

Vessel's Name: "STANVAC SYDNEY" Report No. 915.

It is confirmed that the main propulsion motor
stator coils should have been referred to and not starter coils.

Noted
pm 5/1/53.

x 2/1/53



© 2020

Lloyd's Register
Foundation

003631-003639-0091

Special Damage or repair fee (if any).....
(per Sec. 23) Derrick Test

10. 0. 0.
£ 15. 0. 0.

Received by me,