



Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

7TH FLOOR, SHINKO BUILDING.

8, KAIGAN-DORI, IKUTA-KU

(P. O. BOX NO. 446)

KOBE, JAPAN

25th July, 1957.

Classn(S)

RECEIVED

- 3 JUL 1957

25th June, 1957.

Ans'd

Dear Sir,

"STANVAC SYDNEY"

With reference to your letter of the 10th May regarding our Report No.4196 on the above named ship, we have to inform you that the minimum worn mean diameter of the chain cable recommended to be renewed was 1 15/16" and that 45 fathoms of same were removed from vessel during the survey.

2 1/16

It is regretted that the above information was not clear in our Report.

Yours faithfully,

J.R. Wilson
For the Surveyors.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

003631-003639-0100

003631-003639-0104 12

Vertical stamp: NOTIFICATION

26

