

COPY. OR LONDON

Lloyd's Register of Shipping.

1224

Port

Jacksonville, Fla.

2nd June, 1944

This is to Certify that I have
and the Boiler and Machinery of the
M/V "ONDINA"

and in dry dock - Tampa Shipbuilding Co., Tampa, Fla.

that I have transmitted to the Committee of Lloyd's
of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
carried out to my satisfaction, and that I have
recommended that the record of L. M. C. 5,44, D.B.S. 5,44,
Shaft C. L. last seen 5,44.

in the Register Book in the case of this vessel, when
survey has been completed.

now examined:-

- Cylinders - heads - pistons - valves & gear.
- 4-5-6 - Piston rods - top end pins & brasses - guides &
- connecting rod - crank pins - journals & main bearings.

mediate Shaft

ed Pumps:- Jacket - cooling water - piston cooling water -
all - fuel oil - bilge & sanitary
ing air receiver (upper s.s.)

ndent Auxiliaries:- Steam air compressor - Diesel air com-
- general service pump - jacket cooling water pump - lub.
up - boiler feed pumps (2) - fuel transfer pump - steam
esel engines and generators and starting air receiver
(piston cooling water)
(lub. oil)

P. T. O.
A. Stewart

Engineer Surbemor to Lloyd's Register.

issued upon the terms of the Rules and Regulations of the Society, which provide that:-
mittees of the Society use their best endeavours to ensure that the functions of the Society are properly
understood that neither the Society nor any Member of any of its Committees is under any circumstances
sponsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
Book or other publication of the Society, or for any error of judgment, default or negligence of any of
Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation

003631-003639-0186

in the Register Book.