

ACTION is DEFERRED for drydocking(grounding).

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "RINCON HILLS"

REPORT Jck. No. 2302

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."— (Extract from Sub-Committee's Report, 24/5/92.).

No SPECIAL SURVEY PARTLY HELD. (C)

en due. 12,60.

When proposed to be completed.

Docking: Various damage repairs.

tion of Survey held, &c. See this report.

NOTE D.

DELETE FROM S.R.L.
Drydocking(grounding).

OFFICE NOTE
T.2 Tanker - structural stiffening fitted.
Docking brackets fitted - al.12,54.

S.S.PART HELD.



© 2020

Lloyd's Register
Foundation

003659-003670-0047