

COPY.

LLOYD'S REGISTER OF SHIPPING

2302

COPY FOR LONDON

Port Jacksonville, Florida

March 9, 1960

This is to Certify that I have

Surveyed the ^{part} Machinery of the S.S. "RINCON HILLS" 10635 tons gross of Montreal on February 9, 1960 and subsequent dates whilst vessel was lying on drydock and afloat at Merrill-Stevens D.D. & R. Co., Jacksonville, Fla., for M.B.S., T.S. and part H.S.

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book remain as now classed with fresh record of MBS 2-60 & TS(CL) 2-60 and that her Machinery Classification Record be continued in the Book.

Parts now examined:
(C.S. Items only)

Following may be credited towards Special Survey:

- | | |
|-----------------------------|---------------------------|
| Main Propulsion Turbine | Lube Oil Coolers |
| Main Propulsion Motor | Main Motor Air Cooler |
| Oil Fuel Heaters (3) | Main Generator Air Cooler |
| 2nd Stage Feed Water Heater | Evaporators (2) |
| Deaerator | Main Thrust |
| Coffin Feed Pumps (2) | |

Hand Moller

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AES	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tallshaft Survey
ES	Engine Special Survey	TS(CL)	Tallshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tallshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tallshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150° F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."