

THROUGH BREMEN

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

Telegraphic Address { Inland: Committee, London, Telex  
                          { Overseas: Committee, London, E.C.3

26th March, 1962.

Dear Sirs,

Motorship "REICHENFELS"

This ship was surveyed at Lisbon during January last when various hull and machinery repairs were carried out.

Following this survey it was recommended that set in sheer strake plating etc. in way of Nos.4 and 5 hatches (port side) be specially examined and dealt with as necessary at the next drydocking, and that Nos.3 and 8 crankpin bearings be again examined before the end of January, 1963, and the Committee have continued the class subject to these items receiving attention as stated.

The class is also subject to shell plate No.4 in 2nd strake below sheerstrake between frames 23/26 (port side from aft) being specially examined and dealt with as found necessary by the next drydocking.

Yours faithfully,

c.c. Bremen

pro Clerk to the  
Classification Committee.

Messrs. Deutsche Dampfschiff. Ges. "Hansa",  
Schlachte 6,  
Postfach 4,  
BREMEN,  
Germany.



© 2020

Lloyd's Register  
Foundation

003659-003670-0051