

COPY.

3 SEP 1945

# Lloyd's Register of Shipping.



Port Oslo.

23rd July 1943.

**This is to Certify** that

Sören Wang,

the undersigned Surveyor to this Society did at the request of A/S Drammens Jernstøberi & mek. Verksted, Drammen on the 14th March 1941 and subsequently examine the gascompressors with cylinders and headers, pistons, rods, shaftings and bearings, bedplates, condensers, evaporators with headers, gas and oil separators, brine heater and gas receivers for the ammonia refrigerating machinery to be fitted on board the vessel yard No. 561 at A/B Götaverken, Gothenburg.

The separate parts were carefully examined during construction and were tested and marked as follows:-

NH <sub>3</sub> Gas compressors:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.3.41. S.W.
NH <sub>3</sub> Fluid separators:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.5.43. S.W.
NH <sub>3</sub> Gas receivers:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.5.43. S.W.
Multiple tube type condensers:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.5.43. S.W.
Multiple tube type evaporators:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.5.43. S.W.
Oil separators:-	LLOYDS. AIR. 25 Atm. WATER. 42 Atm. 14.5.43. S.W.
Brine Heater:-	LLOYDS. 3,5 Atm. 14.5.43. S.W.

The parts were found perfectly sound and tight at the above pressure.

The workmanship throughout is good.

The electric welding of the pressure parts were carried out by recognized welders with approved electrodes.

Kr. 190.-

Sign. Sören Wang.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."