

COPY

Ship's name "BRITISH GENERAL" Port ROT. No. 55054
Last survey date 8.12.62.

Class is subject to

set in shell plate G.5 (p.s.f) being
specially examined and dealt with as
necessary next drydocking.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and ~~in~~ drydock)

Temporary repairs to collision damage.

Recommendation

SUBJECT as above and to forecastle deck and
side plating (s.s) etc. being specially examined
and dealt with as necessary next drydocking.

As Now Subject.

IN S.R.L. APPENDIX

Indents in shell plates F.6 & 7 (p.s.f),
F.6 (p.s.a) and F.3 & 4 (s.s.f).



© 2021

Lloyd's Register
Foundation